



# basic education

Department:  
Basic Education  
**REPUBLIC OF SOUTH AFRICA**

## **NATIONAL SENIOR CERTIFICATE**

**GRADE 12**

**MECHANICAL TECHNOLOGY**

**NOVEMBER 2017**

**MARKING GUIDELINES**

**MARKS: 200**

**These marking guidelines consist of 18 pages.**

**QUESTION 1: MULTIPLE-CHOICE QUESTIONS**

- |      |     |     |
|------|-----|-----|
| 1.1  | B ✓ | (1) |
| 1.2  | C ✓ | (1) |
| 1.3  | D ✓ | (1) |
| 1.4  | B ✓ | (1) |
| 1.5  | C ✓ | (1) |
| 1.6  | D ✓ | (1) |
| 1.7  | D ✓ | (1) |
| 1.8  | C ✓ | (1) |
| 1.9  | B ✓ | (1) |
| 1.10 | B ✓ | (1) |
| 1.11 | A ✓ | (1) |
| 1.12 | C ✓ | (1) |
| 1.13 | B ✓ | (1) |
| 1.14 | B ✓ | (1) |
| 1.15 | B ✓ | (1) |
| 1.16 | D ✓ | (1) |
| 1.17 | B ✓ | (1) |
| 1.18 | B ✓ | (1) |
| 1.19 | B ✓ | (1) |
| 1.20 | A ✓ | (1) |

**[20]**

**QUESTION 2: SAFETY****2.1 Surface grinder:**

- Make sure the sparks are of no danger to co-workers. ✓
- Do not force the material onto the grinding wheel. ✓
- Do not plunge grind. ✓
- Bring the material slowly into contact with the grinding wheel. ✓
- Never clean or adjust the machine while it is in motion. ✓
- Use cutting fluid ✓
- Know where the emergency stop is located ✓
- Stop the machine before any adjustments ✓
- Keep tools clear from moving parts ✓

(Any 3x1) (3)

**2.2 Hydraulic press:**

- To make sure there is no leakages. ✓
- To make sure that the readings are accurate. ✓
- To make sure the prescribed pressure is not exceeded. ✓

(2)

**2.3 MIG/MAGS welding:**

- Working area must be well ventilated. ✓
- Make sure electrical parts are properly insulated. ✓
- Make sure the inert gas cylinder is fixed in an upright position. ✓
- Make sure the terminals are connected correctly to the right outlet points. ✓
- The operator should know how to use the equipment. ✓
- The operator must be completely insulated by means of boots, gloves and rubber mats. ✓
- The work area must be partitioned off. ✓
- Use protective equipment. (Overall, gloves, apron, welding helmet etc.) ✓
- Ensure adequate fire precautions. ✓
- See that there is no oil or grease around the machine. ✓
- Ensure that the working area is clean. ✓

(Any 3x1) (3)

**2.4 Spring compressor:**

- Make certain the compressor is strong enough for the spring ✓
- The compressor must be fitted correctly and firmly. ✓
- Ensure that the spring cannot slip out of position. ✓
- A uniform load must be applied. ✓
- Release the load carefully and also uniformly. ✓
- Do not use wire or ropes to compress the spring. ✓
- Do not hit with a hammer. ✓
- The hooks on the clamps should not be warned ✓
- Clamps must be evenly distributed ✓
- Do not exceed the maximum tension ✓

(Any 2x1) (2)

[10]

**QUESTION 3: TOOLS AND EQUIPMENT****3.1 Volt and ammeter:**

- Voltmeter: connected in parallel to a circuit. ✓
- Ammeter: connected in series to a circuit. ✓

(2)

**3.2 Uses of the multimeter:**

- Direct current measurement (DC) ✓
- Alternating current measurement (AC) ✓
- Voltage measurement ✓
- Resistance measurement ✓
- Transistor test ✓
- Diode test ✓
- Continuity test ✓
- Temperature ✓
- Battery test ✓

(Any 4x1)

(4)

**3.3 Compression Test:**

- The piston rings are worn out. ✓✓
- Worn cylinders. ✓✓
- Cracked piston. ✓✓

(Any 1x2)

(2)

**3.4 Tests:**

3.4.1 A beam bending test is to investigate the **deflection / bend** ✓✓ of beams.

(2)

3.4.2 A cylinder leakage tester is to check whether **gases or air leaks** ✓✓ from the cylinders / **valve leak**.

(2)

**[12]**

**QUESTION 4: MATERIALS****4.1 Properties of structures:**

4.1.1 Cementite: hard ✓ and brittle ✓ (2)

4.1.2 Ferrite: soft ✓ and ductile ✓ (2)


**4.2 Heating process of carbon steel:**

4.2.1 Iron-Carbon ✓ Equilibrium ✓ Diagram (2)

4.2.2 A = Ferrite and pearlite ✓  
B = Pearlite and cementite ✓  
C = Ferrite and austenite ✓  
D = Austenite and cementite ✓  
E = Austenite ✓ (5)

4.2.3 700 – 800 °C ✓✓ (2)

**[13]**

**QUESTION 5: TERMINOLOGY****5.1 Screw thread terms:**

5.1.3: **NOTE:** Any other corresponding point on the screw thread (5)

**5.2 Milling processes:**

5.2.1 Up-cut milling ✓ (1)

5.2.2 Down-cut milling ✓ (1)

**5.3 Indexing:**

$$\begin{aligned}
 \text{Indexing} &= \frac{40}{A} \quad \checkmark \\
 &= \frac{40}{22} \\
 &= 1 \frac{18}{22} \times \frac{3}{3} \quad \checkmark \\
 &= 1 \frac{54}{66} \quad \checkmark
 \end{aligned}$$

✓                      ✓                      ✓  
1 full turn and 54 holes on the 66-hole circle (6)

**5.4 Dividing head:**

- 5.4.1 The sector arm save time and removes the possibility of error in counting the number of holes for each move of the index pin. ✓✓ (2)
- 5.4.2 The index plate is equipped with accurate spaced holes on different-diameter circles. Each circle has a different number of holes. These circles allow the crank handle to be given an accurate part of a turn to obtain the desired spacing. ✓✓ (2)
- 5.4.3 The index pin can be set in the crank handle so that it can be dropped into calculated hole and lock the crank the hole circles. ✓✓ (2)
- 5.4.4 Ratio between worm and worm gear: 40:1 ✓✓ (2)

**5.5 Gear terminology:****5.5.1 The pitch-circle diameter 'PCD'**

$$\begin{aligned} \text{Module}(m) &= \frac{PCD}{T} && \checkmark \\ PCD &= m \times T && \checkmark \\ &= 3 \times 94 && \\ PCD &= 282 \text{ mm} && \checkmark \end{aligned} \quad (3)$$

**5.5.2 The outside diameter:**

$$\begin{aligned} \text{Outside diameter} &= PCD + 2m && \checkmark \\ OD &= 282 + 2(3) && \\ OD &= 288 \text{ mm} && \checkmark \end{aligned} \quad (2)$$

**5.5.3 The dedendum:**

Dedendum $b = 1,157m$	or	$b = 1,25m$	✓
$b = 1,157 \times 3$		$b = 1,25 \times 3$	
$b = 3,47 \text{ mm}$		$b = 3,75 \text{ mm}$	✓

(2)

**5.5.4 The cutting depth:**

$\text{Cutting depth} = 2,157 \times m$	or	$\text{Cutting depth} = 2,25 \times m$	✓
$= 2,157 \times 3$		$= 2,25 \times 3$	
$= 6,47 \text{ mm}$		$= 6,75 \text{ mm}$	✓

(2)

**[30]**

**QUESTION 6: JOINING METHODS****6.1 Causes of undercutting:**

- Current setting is too high ✓
- Current setting is too low ✓
- Faulty electrode manipulation ✓
- Arc length is too long ✓
- Welding speed is too fast ✓
- Incorrect electrode size ✓

(Any 2x1) (2)

**6.2 Prevention of slag inclusion:**

- Chip off the slag from the previous weld runs before doing any further welding. ✓✓
- Increase the current setting. ✓✓
- Ensure that the joint is properly cleaned before any welding is done. ✓✓
- Ensure constant current flow. ✓✓
- Arc length must be shorter ✓✓
- Use dry electrodes

(Any 1x2) (2)

**6.3 Liquid dye penetrant test:**

- Dye is sprayed onto the clean surface to be inspected ✓
- Allow a short time for the dye to penetrate, then remove excess dye with a solvent ✓
- Wash surface with water and allow to dry ✓
- When the surface is dry spray a developer on the surface to bring out the colour in the dye which is trapped in the cracks or pin holes ✓

(4)

**6.4 Advantages of using a MIGS/MAGS welding:**

- Operator needs less skills ✓
- Continuous welds can be done without replacing electrodes ✓
- Less cleaning of weld, (No slag to be removed) ✓
- It is a quicker process ✓
- Thin material can be welded easily ✓
- Can weld in any position ✓
- Create a better finish ✓
- High deposition rate ✓
- Less distortion ✓

(Any 3x1) (3)

**6.5 Gas flow meter:**

Control the flow of rate of shielding gas ✓ and measure the flow rate. ✓

(2)



**6.6 MIGS/MAGS welding process:**

A = Melted welding pool / Parent metal / Weld metal / Weld ✓

B = Contact nozzle / Weld pistol / gun ✓

C = Gas shroud / Weld pistol / gun ✓

D = Shielding gas ✓

E = Earth clamp / Skelm / Earth cable ✓

(5)

**6.7 Shielding gas in MIGS/MAGS:**

• To control the welding arc ✓✓

• Shield the molten pool from atmospheric gases ✓✓

(Any 1x2)

(2)

**6.8 Earth cable:**

• To complete the circuit ✓✓

• To maintain constant current ✓✓

• To prevent electric shock ✓✓

(Any 1x2)

(2)

**6.9 THREE types of gasses used for MIGS/MAGS welding:**

• Argon ✓

• Teral ✓

• CO<sub>2</sub> ✓

• Helium ✓

• Gas mixture ✓


(Any 3x1)

(3)

**[25]**

**QUESTION 7: FORCES**

7.1



$$\begin{aligned} \checkmark \\ \Sigma HC &= 300\cos 50^\circ - 200\cos 30^\circ + 400 \\ &= 192,84 \checkmark - 173,21 \checkmark + 400 \\ &= 419,63 \text{ N } \checkmark \end{aligned}$$

$$\begin{aligned} \checkmark \\ \Sigma VC &= 200\sin 30^\circ - 100 + 300\sin 50^\circ \\ &= 100 \checkmark - 100 + 229,81 \checkmark \\ &= 229,81 \text{ N } \checkmark \end{aligned}$$

OR

Horizontal component ✓	Magnitudes	Vertical component ✓	Magnitudes
$-200\cos 30^\circ$	$-173,21 \text{ N } \checkmark$	$200\sin 30^\circ$	$100 \text{ N } \checkmark$
$300\cos 50^\circ$	$192,84 \checkmark$	$300\sin 50^\circ$	$229,81 \text{ N } \checkmark$
$400 \text{ N}$	$400 \text{ N}$	$0$	$0 \text{ N}$
$0$	$0 \text{ N}$	$-100$	$-100 \text{ N}$
<b>TOTAL</b>	<b><math>419,63 \text{ N } \checkmark</math></b>	<b>TOTAL</b>	<b><math>229,81 \text{ N } \checkmark</math></b>

$$R^2 = HC^2 + VC^2 \checkmark$$

$$R = \sqrt{419,63^2 + 229,81^2}$$

$$R = 478,44 \text{ N } \checkmark$$

$$\tan \theta = \frac{VC}{HC} \checkmark$$

$$= \frac{229,81}{419,63}$$

$$\theta = 28,71^\circ \checkmark$$

$$R = 478,44 \text{ N at } 28,71^\circ \text{ north from east } \checkmark$$

(13)

**7.2 Stress and Strain:****7.2.1 Stress in the bar:**

$$A = \frac{\pi D^2}{4} \quad \checkmark$$

$$= \frac{\pi \times 0,056^2}{4} \quad \checkmark$$

$$= 2,46 \times 10^{-3} m^2 \quad \checkmark$$

$$\sigma = \frac{F}{A} \quad \checkmark$$

$$= \frac{40 \times 10^3}{2,46 \times 10^{-3}} \quad \checkmark$$

$$= 16260162,6 Pa \quad \checkmark$$

$$= 16,26 \times 10^6 Pa$$

$$= 16,26 MPa$$

(5)

**7.2.2 Strain:**

$$\varepsilon = \frac{\sigma}{E} \quad \checkmark$$

$$\varepsilon = \frac{16,26 \times 10^6}{90 \times 10^9} \quad \checkmark$$

$$= 0,18 \times 10^{-3} \quad \checkmark$$

(3)

**7.2.3 Change in length:**

$$\varepsilon = \frac{\Delta l}{ol} \quad \checkmark$$

$$\Delta l = \varepsilon \times ol \quad \checkmark$$


$$= (0,18 \times 10^{-3}) \times 0,85$$

$$= 0,15 \times 10^{-3} m$$

$$OR \quad \checkmark$$

$$= 0,15 mm$$

(3)

7.3 **Moments:****Calculate A. Moments about B:**

$$\sum \text{RHM} = \sum \text{LHM}$$

$$(A \times 12) = (960 \times 6) + (750 \times 8) \quad \checkmark \checkmark$$

$$\frac{12A}{12} = \frac{5760 + 6000}{12}$$

$$A = 980 \text{ N} \quad \checkmark$$

**Calculate B. Moments about A:**

$$\sum \text{LHM} = \sum \text{RHM}$$

$$(B \times 12) = (750 \times 4) + (960 \times 6) + (300 \times 12) \quad \checkmark \checkmark$$

$$12B = 3000 + 5760 + 3600$$

$$\frac{12B}{12} = \frac{12360}{12}$$

$$B = 1030 \text{ N} \quad \checkmark$$

(6)

**[30]**

**QUESTION 8: MAINTENANCE**

- 8.1 **Pour point:**  
The lowest temperature ✓ at which a liquid will flow. ✓ (2)
- 8.2 **Advantages of cutting fluids:**
- Keep the work piece and cutting tool cool ✓
  - It prolongs the life of the cutting tool ✓
  - Ensure a better finish ✓
  - It washes the cuttings/swarf away ✓
  - It protects the machine by making the cutting process easier ✓
  - Prevents rust ✓
  - It increases the productivity because ✓
  - It is possible to cut faster ✓
  - It lubricates the machine ✓
- (Any 3x1) (3)
- 8.3 **'ATF':**  
Automatic transmission fluid ✓✓ (2)
- 8.4 **Main parts of a clutch:**  
Pressure plate ✓ clutch plate ✓ release bearing (Thrust bearing) ✓ (3)
- 8.5 **Results of a stretched chain:**
- The chain weakens ✓
  - Generates friction ✓
  - Vibration occurs ✓
  - Becomes noisy ✓
  - Derails easily ✓
  - Tends to break easily ✓
- (Any 3x1) (3)
- 8.6 **Causes of belt slip:**
- Incorrect tension (loose) ✓
  - Oil on the contact surfaces ✓
  - Worn belts ✓
  - Incorrect pulley alignment ✓
  - Overloading ✓
  - Not the correct size ✓
- (Any 2x1) (2)

**[15]**

**QUESTION 9: SYSTEM AND CONTROLS****9.1 Gear drives:****9.1.1 Rotation frequency of the output shaft:**

$$\frac{N_F}{N_A} = \frac{T_A \times T_C \times T_E}{T_B \times T_D \times T_F}$$

$$N_F = \frac{T_A \times T_C \times T_E}{T_B \times T_D \times T_F} \times N_A \quad \checkmark$$

$$N_F = \frac{30 \times 20 \times 50}{40 \times 60 \times 70} \times 2300 \quad \checkmark$$

$$= 410,71 \text{ r/min} \quad \checkmark \quad (3)$$

**9.1.2 Velocity Ratio:**

$$VR = \frac{N_{\text{INPUT}}}{N_{\text{OUTPUT}}} \quad \checkmark$$

$$= \frac{2300}{410,71} \quad \checkmark$$

$$= 5,6:1 \quad \checkmark$$

**or**

$$VR = \frac{N_{\text{OUTPUT}}}{N_{\text{INPUT}}} \quad \checkmark$$

$$= \frac{410,71}{2300} \quad \checkmark$$

$$= 1:0,178 \quad \checkmark \quad (2)$$

**9.2 Belt Drives:****9.2.1 Rotation frequency of the driven pulley:**

$$V = \pi D n \quad \checkmark \checkmark \checkmark$$

$$n = \frac{V}{\pi D}$$

$$= \frac{32}{\pi \times (0,26)}$$

$$n_{\text{r/min}} = 39,18 \times 60$$

$$n_{\text{r/min}} = 2350,6 \text{ r/min} \quad (3)$$

**9.2.2 Tensile force in the tight side:**

$$\frac{T_1}{T_2} = 2,5 \quad \checkmark$$

$$T_1 = 2,5 \times T_2 \quad \checkmark$$

$$= 2,5 \times 140$$

$$= 350 \text{ N} \quad \checkmark \quad (2)$$

**9.2.3 Power transmitted:**

$$P = (T_1 - T_2)v \quad \checkmark$$

$$P = (350 - 140) \times 32 \quad \checkmark$$

$$= 6720 \text{ Watts} \quad \checkmark \quad (3)$$

**9.3 Hydraulics:****9.3.1 Fluid pressure:**

$$A_A = \frac{\pi D^2}{4} \quad \checkmark$$

$$= \frac{\pi 0.02^2}{4} \quad \checkmark$$

$$= 0,31 \times 10^{-3} \text{ m}^2$$

$$p_A = \frac{F}{A_A} \quad \checkmark$$

$$= \frac{300}{0,31 \times 10^{-3}} \text{ Pa}$$

$$= 967741,94 \text{ Pa} \quad \checkmark$$

$$= 0,97 \times 10^6 \text{ Pa}$$

$$= 0,97 \text{ MPa}$$

(4)

**9.3.2 Stroke at piston B:**

$$A_B = \frac{\pi D^2}{4} \quad \checkmark$$

$$= \frac{\pi 0.075^2}{4}$$

$$= 4,42 \times 10^{-3} \text{ m}^2 \quad \checkmark$$

$$V_B = V_A$$

$$A_B \times L_B = A_A \times L_A \quad \checkmark$$

$$L_B = \frac{A_A \times L_A}{A_B}$$

$$= \frac{(0,31 \times 10^{-3}) \times 185}{4,42 \times 10^{-3}}$$

$$= 12,98 \text{ mm} \quad \checkmark$$

(4)

**9.4 Traction control:**

It prevents the wheels from spinning ✓ ✓

(2)

**9.5 Safety belt:**

Safety belts need to be activated (buckle up) by the driver/passenger ✓ ✓

(2)

**[25]**

**QUESTION 10: TURBINES**

- 10.1 **Water turbine:**
- Waterwheel ✓
  - Pelton ✓
  - Turgo ✓
  - Michell-Banki ✓
  - Jonval turbine ✓
  - Reverse overshot waterwheel ✓
  - Archimedes' screw turbine ✓
- (Any 1x1)** (1)
- 10.2 **Runaway speed of a water turbine:**  
Runaway speed of a water turbine is its speed at full flow ✓ and with no shaft load ✓
- (2)
- 10.3 **Water turbine:**
- 10.3.1 **Type of turbine:**
- Reaction turbine ✓
  - Kaplan turbine ✓
- (Any 1x1)** (1)
- 10.3.2
- A. Wicket gate ✓
  - B. Rotor ✓
  - C. Stator ✓
  - D. Shaft ✓
  - E. Water flow ✓
  - F. Blades ✓
- (6)
- 10.3.3 **Advantages of water turbine:**
- Water turbine blades continue to turn on cloudy windless days unlike sun and windy system. ✓
  - No water is consumed in this process ✓
  - More reliable ✓
  - Environmentally friendly with no pollution ✓
  - More economical than steam turbines ✓
  - Can be mounted vertically to take up less space ✓
- (Any 3x1)** (3)
- 10.4 **Function of turbo and superchargers:**  
To increase ✓ volumetric efficiency ✓ of an internal combustion engine.
- (2)
- 10.5 **Compressor used in a turbocharger:**  
Centrifugal ✓
- (1)
- 10.6 **Turbocharger:**  
Exhaust gasses ✓
- (1)



**10.7 Advantage of a turbocharger:**

- It is driven by exhaust gasses ✓
- No power from engine is used ✓
- Power loss above sea level is eliminated ✓
- More power is developed compared to a similar vehicle without a turbocharger ✓
- Less fuel is used compared to engine mass ✓
- To increase volumetric efficiency ✓

(Any 1x1) (1)

**10.8 Advantage of a steam turbine:**

- It is compact ✓
- No lubrication is needed ✓
- It is more economical ✓
- Converts heat energy into mechanical energy ✓
- Greater thermal efficiency ✓
- Direct drive ✓
- Low maintenance ✓
- High power to weight ratio ✓

(Any 2x1) (2)

[20]

**GRAND TOTAL: 200**